



Release Notes

OTU-5000 SmartOTU FTH-5000 Standalone Mode

V22.74 – 26 May 2023

Bugs Fixing:

- 9543: OSX not detected because of calibration corruption
- 9521: SHDC card is sometimes unreachable

V22.68 – 11 April 2023

Bugs Fixing:

- 9462: Automatic Measurement crash

V22.64 – 9 March 2023

Bugs Fixing:

- 9412: Internal Communication alarm on OTU5k after upgrade to 22.58
- 9384: Test not monitored because of wrong test ordering





V22.58 – 6 February 2023

Bugs Fixing:

- 9201: Attenuation alarm event flapping
- 9202: Injection alarm event flapping
- 9339: Alarms cleared on wrong test when re-referencing
- 9328: Issue with password after upgrade
- 8338: CPU Temperature Alarm Change
- 9262: Impossible to deploy license if the file containing unsent emails is too big

Enhancements:

- 9176: FTH-5000 EXTENDED TEMPERATURE RANGE FOR OTDR AT 1650NM

V21.52 – 24 November 2022

Bugs Fixing:

- 8947: Wrong position if Last Marker when the end of fiber is not clearly visible
- 9030: False Alarm caused by temperature variation
- 9089: Link Loss "deviation from reference" not correct

Enhancements

- 9054: Universal Optical Switch Support
- 9104: New Alarm (severity Warning) when it is detected that the fiber end changed after the fiber was repaired. The alarm message is "Fiber change, New reference required". This alarm is also transferred by SNMP Traps with the following values:
 - o JdsuOtuAlarmType: optic(1)
 - o optical alarm specific problem: attenuation(1),
 - o JdsuOtuOpticalAlarmSubProblem: attenuation(3),
 - o jdsuOtuAlarmEventEntryOpticalAlarmProbableCauseText: « Fiber changed, New reference required»



V21.44 – 14 June 2022

Bugs Fixing:

- 8789: Alarm level is not correct in case of fiber cut
- 8857: Wrong localization with low thresholds

V21.36 – 21 January 2022

Bugs Fixing:

- 8699: Issue with long IPV6 address

V21.30 – 28 December 2021

Bugs Fixing:

- 8427: ProbableCause field empty in email
- 8623: Upgrade from 17.18 to 21.16

V21.26 – 22 November 2021

Bugs Fixing:

- 8427: Impossible to set full IPv6 address for snmp manager through API
- 8420: Flash monitoring / The monitoring is stopped when signal is received
- 8402: Flash monitoring / Alarm OTDR trace is missing
-

Enhancements

- 8404: link name Added to email subject
- 8386: Test On Demand thru SNMP
- Synchronization with NTP server:



- otu:api:conf:ntp:enable false/true
- otu:api:conf:ntp:conf static, NTP server IP Address
-
- examples
- otu:api:conf:ntp:enable true
- otu:api:conf:ntp:conf static, "10.49.2.132"
- otu:api:conf:ntp:conf static, "pool.ntp.org"



-

V21.10 – 26 July 2021

Bugs Fixing:

- 8319: Flash monitoring / APD tension drift

Enhancements

- 8273: Flash monitoring / Link name included with all the notifications
- 8235: Flash monitoring / Files download from UI

V20.22 – 6 May 2021

Bugs Fixing

- 8232: shortAcq started on detection/localisation without SmartAcq

V20.16 – 25 Feb 2021

Enhancements

- 8103: Flash monitoring for flapping diagnostic

Bugs Fixing

- 8102 : "missing ref trace" on fiber degradation after upgrade to 20.10

V20.10 – 8 Feb 2021

Bugs Fixing

- 7763 : Communications errors with external switch



V18.94 – 18 Nov 2020

Bugs Fixing

- 7740 : False alarm temperature in SmartAcq mode (short + Long pulse) when traffic is amplified

V18.86 – 1 July 2020

Enhancements

- 7451: Support of 144 ports optical switch

Bugs Fixing

- 7646 : blocking after upgrade when alarms are present
- 7656 :: False alarm on reflective fiber end

V18.80 – 1 June 2020

Enhancements

- 7333: SNMP Walk
- 7200: ZTP

Bugs Fixing

- 7341: Autoconfiguration issue

V18.58 – 4 December 2019

Bugs Fixing

- 7307: Main Led never lights or Flash to indicate Local mode

V18.54 – 31 October 2019



Enhancements

- Dual pulse acquisition reducing the front end dead zone to few meters ⁽¹⁾
- Monitoring algorithm enabling Fiber fault location from few meters after the OTDR up to few meters before the end of fiber. ⁽¹⁾
- Root cause of the fiber fault (Connector or fiber)
- High sensitivity monitoring available with OTDR E81162D and E8115D. A software license is required. Consult Viavi sales or partners.
- Web Services REST Application Program Interface. A software license is required. Consult Viavi sales or partners.
- Number of ports display in SmartOTU monitoring view has increased from 24 to 48 per page

(1): After the upgrade there is a specific process described in the embedded user manual to apply the monitoring algorithm and dual pulse acquisition.